

FIAT PANDA 1.2 8V 69CV CLIMBING EURO 5 6365 HHZ (MOTORCADE CARS MC1583)



194.154Kms



26/01/2012



70 BHP



PETROL



MANUAL



150 g/km



OPTIONS

Extras Accessories:
3rd seat belt - 5 seats -2 head restraints
Air conditioning
Fog
lights Stability control ESP
Spare wheel normal size

Total options price : 1807,00 €

EQUIPMENTS

Vehicle type tourism
Bodywork hatchback hatchback
Color White
No. of doors 0
Power N / A
Displacement 1,242 cm 3
Motor Gasoline
Date 01/26/2012
Kilometres 194,154
Enrollment 6365HHZ
Frame ZFA16900004061957

DESCRIPCIÓN ADICIONAL

DIRECT FROM ALD AUTOMOTIVE TO

(MOTORCADE CARS MC1583)

Contacte con nosotros

Motorcade Cars, S.L.
Km 2.2 Camino Viejo De Coin Mijas 29649
952 666 116 or 665 960 064
motorcadespain@gmail.com
www.motorcadespain.com

PRICE
€5995,00

Extras Accessories:

- 3rd seat belt - 5 seats -2 head restraints
- Air conditioning
- Fog
- lights Stability control ESP
- Spare wheel normal size

Date Ent. Workshop	Date Depart Workshop	Provider	Detail	Number of Kilometers	Tires Changed
05/08/2020	05/08/2020	LOS ARCOS SCL AUTOMOBILE WORKSHOPS AND SPARE PARTS	Replace battery Cost Management Authorization Cost Management Authorization Repair of engine accessories Replace battery Body repairs	192,40	
02/28/2020	02/28/2020	Euomas ter-Rodi	Forwards	183,67	two
10/30/2019	10/30/2019	LOS ARCOS SCL AUTOMOBILE WORKSHOPS AND SPARE PARTS	Cost Management Authorization Review 180000Kms. Replace brake fluid Replace oil filter Replace air filter Replace pollen filter Replace oil Replace front brake pads Check / Refill levels Check 180000Kms. Replace air filter Replace pollen filter Replace oil Replace brake fluid Replace oil filter Replace front brake pads Steering system repairs Steering system repairs Check / Refill levels Cost Management Authorization Waste rate	183,67	
10/23/2019	10/23/2019	FIRST STOP SOUTH WEST SAU. - TERUEL	Rear	183,24	two
09/16/2019	09/30/2019	LOS ARCOS SCL AUTOMOBILE WORKSHOPS AND SPARE PARTS	Deference Cost Management Authorization Replace fuse box replace electrical installation section replace electrical installation section Repair motor accessories replace electrical installation section replace electrical installation section Replace electrical installation section Replace fuse box replace electrical installation section	180,70	
11/28/2018	11/28/2018	LOS ARCOS SCL AUTOMOBILE WORKSHOPS AND SPARE PARTS	Cost Management Authorization Review 160000Kms. Replace oil filter Replace spark plugs Replace pollen filter Replace oil Check / Refill levels Revision 160000Kms. Replace spark plugs Replace pollen filter Replace oil Replace oil filter Check / Fill levels Cost Management Authorization Waste rate	162,94	

10/17/2018	10/17/2018	Euromaster-Franchisee	Front and Rear	159,972	4
04/10/2018	04/10/2018	LOS ARCOS SCL AUTOMOBILE WORKS HOPS AND SPARE PARTS	Cost Management Authorization Repair of controls / switches Repair of controls / switches Replace steering wheel Repairs on steering system Cost Management Authorization Repair of engine accessories	159,422	
07/31/2018	07/31/2018	LOS ARCOS SCL AUTOMOBILE WORKS HOPS AND SPARE PARTS	Cost Management Authorization Diagnosis Replace lamps in exterior lighting Replace air conditioning pipes Charge air conditioning Replace lamps in exterior lighting Trims Replace air conditioning pipes Replace air filter Replace coolant tank Repairs on bodywork Cost Management Authorization Diagnosis	157,292	
08/29/2017	08/29/2017	LOS ARCOS SCL AUTOMOBILE WORKS HOPS AND SPARE PARTS	Lighthouse Revision Authorization Management Cost 140000Kms. Replace pollen filter Replace oil filter Replace Faro Faro oil Body repairs Overhaul 140000Kms. Replace oil Replace oil filter Replace pollen filter Cost Management Authorization Waste rate	140,342	
06/23/2017	06/23/2017	FIRST STOP SOUTH WEST SAU. - TERUEL	Front and Rear	135,872	4
06/23/2017	06/23/2017	FIRST STOP OFFICE / CENTRAL (NO WORKS HOP)	Replace lamps in outdoor lighting Replace lamps Trims	135,832	
12/27/2016	12/27/2016	LOS ARCOS SCL AUTOMOBILE WORKS HOPS AND SPARE PARTS	Cost Management Authorization Replace clutch assembly Replace seals / seals in gearbox Replace seals / seals in gearbox Replace steering ball joints Renew / Replace oil Replace clutch assembly Replace new gearbox Replace seals / seals in gearbox Replace seals / gaskets in gearbox Replace left front transmission Replace steering ball joints Cost Management Authorization Renew / Replace oil	123,346	

