

FIAT PANDA 1.3 LOUNGE 75CV DI  SEL 8041 JML MOTORCADE CARS MC1628



218.575Kms



14/03/2016



75 BHP



DIESEL



MANUAL



104 g/km



OPCIONES

Extras Accessories:

3 rear seat belts, 3rd rear headrest, 5 seats
Blue & Me
Fog lights
Steering wheel
controls (10 buttons) Extra-serial pastel paint.

Importe total de las opciones: 937,00  .

EQUIPAMIENTO

Vehicle type tourism
Bodywork hatchback hatchback
Colour Blanco
No. of doors 5
Power 75 BHP
Displacement 1,248 cm 3
Motor Diesel
Date 03/14/2016
Kilometres 218,575
Enrollment 8041JML
Frame ZFA31200003493092

DESCRIPCI  N ADICIONAL

DIRECT FROM ALD AUTOMOTIVE TO

MOTORCADE CARS MC1628

Contact Us

Motorcade Cars, S.L.
Km 2.2 Camino Viejo De Coin Mijas 29649
952 666 116 or 665 960 064
motorcadespain@gmail.com
www.motorcadespain.com

PRECIO :
 5995,00

Extras Accessories:

3 rear seat belts, 3rd rear headrest, 5 seats

Blue & Me

Fog lights

Steering wheel

controls (10 buttons) Extra-serial pastel paint.

| Date Ent. Workshop | Date Depart Workshop | Provider | Detail | Number of Kilometers | Tires Changed |
|--------------------|----------------------|------------------------|---|----------------------|---------------|
| 07/15/2020 | 07/15/2020 | SOLEDAD TIRES | Cost Management Authorization Replace front brake pads Deference Replace front brake pads Steering system repairs Steering system repairs Management Cost Deference Authorization | 214,996 | |
| 07/14/2020 | 07/14/2020 | TIRES HNOS. ARROYO, SL | Forwards | 214,996 | 2 |
| 05/04/2020 | 05/04/2020 | SOLEDAD TIRES | Puncture Replace lamps in exterior lighting Replace lamps in exterior lighting Replace lamps in exterior lighting Replace lamps Trims Replace lamps Trims Replace lamps Trims Puncture | 210,690 | |
| 02/14/2020 | 02/26/2020 | SOLEDAD TIRES | Deference Cost Management Authorization Replace catalyst Repair engine accessories Replace catalyst | 208,025 | |
| 01/31/2020 | 01/31/2020 | SOLEDAD TIRES | Replace catalyst | 205,980 | |
| 01/27/2020 | 01/27/2020 | SOLEDAD TIRES | Cost Management Authorization Replace lamps in exterior lighting Replace lamps in exterior lighting Replace lamps in exterior lighting Puncture Diagnosis Replace lamps Replace lamps Trims Repair engine accessories Puncture Diagnosis Cost Management Authorization Replace lamps Trims | 205,975 | |
| 01/08/2020 | 01/08/2020 | SOLEDAD TIRES | Cost Management Authorization Replace lamps in exterior lighting Replace lamps in exterior lighting Replace oil filter Replace oil Replace antifreeze Check / Fill levels Revision 200000Kms. Replace pollen filter. Replace air filter. Replace brake fluid. Replace lamps. Replace lamps. Trims Revision 200000Kms. Replace brake fluid Replace air filter Replace pollen filter Replace oil Body repairs Cost Management Authorization Replace antifreeze Check / fill levels Residue rate | 202,650 | |
| 12/26/2019 | 12/26/2019 | SOLEDAD TIRES | Puncture Replace lamps in exterior lighting Replace lamps Trims Puncture | 198,950 | |
| 12/12/2019 | 12/12/2019 | SOLEDAD TIRES | Cost Management Authorization Replace lamps in exterior lighting Replace lamps in exterior lighting Replace lamps in exterior lighting Diagnosis Replace lamps in exterior lighting Replace lamps Trims Replace lamps in exterior lighting Diagnosis Management Cost Authorization | 197,930 | |
| 11/26/2019 | 11/27/2019 | SOLEDAD TIRES | Cost Management Authorization Replace antifreeze Replace water pump Replace antifreeze Replace new alternator Replace water pump Replace new alternator | 194,340 | |
| 11/21/2019 | 11/21/2019 | SOLEDAD TIRES | Replace lamps in outdoor lighting Replace lamps | 194,330 | |

| | | | | | |
|------------|------------|-------------------------|---|---------|---|
| 11/18/2019 | 11/18/2019 | SOLEDAD TIRES | Prick | 194,336 | |
| 11/14/2019 | 11/15/2019 | SOLEDAD TIRES | Replace lamps in outdoor lighting Replace lamps in outdoor lighting Replace lamps Replace lamps | 190,909 | |
| 09/23/2019 | 09/24/2019 | SOLEDAD TIRES | Cost Management Authorization Replace oil filter Replace oil Revision 180000Kms. Review 180000Kms. Replace fuel filter Replace oil Body repairs Cost Management Authorization Waste rate | 182,809 | |
| 09/17/2019 | 09/17/2019 | SOLEDAD TIRES | Check / fill levels Replace antifreeze Replace antifreeze Check / fill levels | 182,806 | |
| 09/16/2019 | 09/16/2019 | TIRES HNOS. AR ROYO, SL | Forwards | 181,751 | 2 |
| 09/13/2019 | 09/13/2019 | SOLEDAD TIRES | Replace lamps in outdoor lighting Replace lamps | 181,751 | |
| 07/10/2019 | 07/10/2019 | SOLEDAD TIRES | Cost Management Authorization Puncture Replace front windscreen wiper blades Replace front windscreen wiper blades Replace lamps in exterior lighting Replace lamps in exterior lighting Replace oil Charge air conditioning Check / Refill levels Annual inspection Replace fuel filter Replace lamps in exterior lighting Replace lamps in exterior lighting Annual Replace fuel filter Check / Fill levels Replace wiper blades Cost Management Authorization Replace oil Check / Fill levels Puncture Waste rate | 170,266 | |
| 03/18/2019 | 03/18/2019 | SOLEDAD TIRES | Replace lamps in outdoor lighting Replace lamps in outdoor lighting Replace lamps in outdoor lighting Replace lamps in outdoor lighting Replace lamps Trims Replace lamps Trims | 164,661 | |
| 02/14/2019 | 02/21/2019 | SOLEDAD TIRES | Cost Management Authorization Replace lamps in exterior lighting Replace lamps in exterior lighting Repairs in lubrication system Replace lamps in exterior lighting Replace battery Replace lamps in exterior lighting Replace electric fan Repairs in lubrication system Replace antifreeze Diagnosis Replace battery Replace electric fan | 163,246 | |
| 01/10/2019 | 01/10/2019 | SOLEDAD TIRES | Revision 160000Kms. Replace brake fluid Replace air filter Replace pollen filter Replace oil Repair oil pan Replace oil filter Replace oil Replace lamps in exterior lighting Replace antifreeze Replace front wiper blades Cost Management Authorization Replace lamps Replace front wiper blades Management Replace front windscreen wiper management Authorization Replace oil Replace oil filter Replace oil Service 160000Kms. Revision 160000Kms. Replace air filter Replace pollen filter Replace brake fluid Waste rate | 161,874 | |
| 11/19/2018 | 11/19/2018 | SOLEDAD TIRES | Replace lamps in outdoor lighting Replace lamps Trims | 159,504 | |
| 10/15/2018 | 10/15/2018 | SOLEDAD TIRES | Replace lamps in outdoor lighting Replace lamps in outdoor lighting | 158,095 | |
| 09/26/2018 | 09/26/2018 | SOLEDAD TIRES | Replace lamps in outdoor lighting Replace lamps in outdoor lighting Replace lamps Replace lamps Trims Replace lamps Trims | 157,255 | |
| 08/20/2018 | 08/20/2018 | SOLEDAD TIRES | Prick | 155,112 | |

