

Service Record


FIRST SERVICE **1**
DUE AT KM **5.955**

We certify that the First Service has been completed in accordance with the manufacturer's schedule applicable to your vehicle

DEALER STAMP

C. DE SALAMANCA, S. A.
Ctra. de Cadiz, Km. 17,1
Teléfs. 952 78 52 50 - 952 78 52 54
Fax: 952 78 03 66
SAN PEDRO DE ALCANTARA (Malaga)

SIGNATURE DATE **19/02/01**



This page is intentionally blank

Service Record

MAINTENANCE SERVICE 2

DUE AT KM 20.000 km

RECORDED KM 20.000

Brake fluid replaced? YES NO

Camschaft drivebelt replaced? YES NO

We certify that this Service/Anti-Corrosion Warranty Inspection has been completed in accordance with the manufacturer's schedule applicable to your vehicle

ANTI-CORROSION WARRANTY

Are body or paint repairs required? YES NO

If yes, list requirements below

SIGNATURE [Signature] DATE 15/10/02

SIGNATURE _____ DATE _____

USE APPROPRIATE STAMP FOR SERVICE/ANTI-CORROSION WARRANTY INSPECTION

C. DE SALAMANCA, S.A.
 Telfs.: 278 52 50/54 - Fax: 278 63 66
 Carretera de Cádiz, Km. 17
 SAN PEDRO ALCAZAR DE SAN JUAN

ABOVE REPAIRS COMPLETED - DEALER STAMP

Service Record

MAINTENANCE SERVICE 3

DUE AT KM 40.000 km

RECORDED KM 50.000

Brake fluid replaced? YES NO

Camschaft drivebelt replaced? YES NO

We certify that this Service/Anti-Corrosion Warranty Inspection has been completed in accordance with the manufacturer's schedule applicable to your vehicle

ANTI-CORROSION WARRANTY

Are body or paint repairs required? YES NO

If yes, list requirements below

SIGNATURE [Signature] DATE 07/10/04

SIGNATURE _____ DATE _____

USE APPROPRIATE STAMP FOR SERVICE/ANTI-CORROSION WARRANTY INSPECTION

SERTASA
 Avda. de Valdeques, 321
 29004 MALAGA
 Telfs. 952 17 68 25 - Fax 952 17 64 97

ABOVE REPAIRS COMPLETED - DEALER STAMP

Service Record

MAINTENANCE SERVICE

6

DUE AT 02/01/2011
RECORDED KM 124 000

Brake fluid replaced? YES NO

Camshaft drivebelt replaced? YES NO

We certify that this Service/Anti-Corrosion Warranty Inspection has been completed in accordance with the manufacturer's schedule applicable to your vehicle.



SIGNATURE: *Jorge Novales* DATE: _____

ANTI-CORROSION WARRANTY

Are body or paint repairs required? YES NO
If yes, list requirements below



SIGNATURE: _____ DATE: _____

Service Record

MAINTENANCE SERVICE

15K7

DUE AT 06/01/2013
RECORDED KM 134 000

Brake fluid replaced? YES NO

Camshaft drivebelt replaced? YES NO

We certify that this Service/Anti-Corrosion Warranty Inspection has been completed in accordance with the manufacturer's schedule applicable to your vehicle.



SIGNATURE: *André Pöhl* DATE: _____

ANTI-CORROSION WARRANTY

Are body or paint repairs required? YES NO
If yes, list requirements below



SIGNATURE: _____ DATE: _____

Service Record

MAINTENANCE SERVICE 8

DUE AT _____ KM

RECORDED KM 1115

Brake fluid replaced? YES NO

Cams/hat drivebelt replaced? YES NO

Handwritten signature

We certify that this Service/Anti-Corrosion Warranty Inspection has been completed in accordance with the manufacturer's schedule applicable to your vehicle.

ANTI-CORROSION WARRANTY

Are body or paint repairs required? YES NO

If yes, list requirements below

USE APPROPRIATE STAMP FOR SERVICE/ANTI-CORROSION WARRANTY ANNUAL INSPECTION

BOSCH REVISION

SIGNATURE _____ DATE _____

Handwritten signature and date: 29/12/2015

ABOVE REPAIRS COMPLETED - DEALER STAMP

SIGNATURE _____ DATE _____

Service Record

MAINTENANCE SERVICE 9

DUE AT _____ KM

RECORDED KM 1873

Brake fluid replaced? YES NO

Cams/hat drivebelt replaced? YES NO

Handwritten signature

We certify that this Service/Anti-Corrosion Warranty Inspection has been completed in accordance with the manufacturer's schedule applicable to your vehicle.

ANTI-CORROSION WARRANTY

Are body or paint repairs required? YES NO

If yes, list requirements below

USE APPROPRIATE STAMP FOR SERVICE/ANTI-CORROSION WARRANTY ANNUAL INSPECTION

BOSCH REVISION

SIGNATURE _____ DATE _____

Handwritten signature and date: 20/1/2016

ABOVE REPAIRS COMPLETED - DEALER STAMP

SIGNATURE _____ DATE _____