

Registration Number
 Manufacturer
 Model
 Type
 First Registration
 Parking Lot Number

 Mileage 176 820
 Number of Doors
 Number of Seats
 Colour

 Body Type
 Fuel Type
 Cylinder Capacity
 Horse Power
 Transmission Type

 VIN Number
 Object Number

- With Technical File
- With Maintenance Book
- With Circulation Permit
- With second key
- Metallic paint
- Without anti-theft screw tires
- Telematic - OctoBox
- _7 seats
- _ABS
- _Central lock
- _Climator
- _Speed control
- _Power steering
- _Power windows
- _Genon Feeds
- _Alloy wheels
- _Browser
- _On-board computer
- _Radio CD
- _Sensor de parking
- _Leather upholstery
- _Solar roof
- _Mobile phone
- _Traction to 4 wheels (4x4)
- _Automatic transmission
- _Multifunction steering wheel

0133-JCK
 MITSUBISHI
 OUTLANDER
 220 Di-D Car Auto 4wd
 30/01/2015
 A176820

 176 820 Km
 5
 7
 White

 SUV 4x4
 Diesel
 2268
 150 HP
 AUTOMATIC

 JMBXLG6WEZD03420
 4437762



Maintenance and Repair Report

MITSUBISHI OUTLANDER (0133-JCK)

Mileage	Description	Serviced by	Date
169 638 Km	VARIOUS LIQUIDS	ANLU AUTOMOCION SL	10/16/2018
169 638 Km	MECHANICAL WORKMANSHIP	ANLU AUTOMOCION SL	10/16/2018
169 638 Km	MECHANICS	ANLU AUTOMOCION SL	10/16/2018
169 638 Km	REVISION	ANLU AUTOMOCION SL	10/16/2018
151 173 Km	MECHANICAL WORKMANSHIP	ANLU AUTOMOCION SL	04/18/2018
151 173 Km	LIVE MATERIALS	ANLU AUTOMOCION SL	04/18/2018
151 173 Km	MECHANICS	ANLU AUTOMOCION SL	04/18/2018
151 173 Km	FRONT PILLS	ANLU AUTOMOCION SL	04/18/2018
151 173 Km	REVISION	ANLU AUTOMOCION SL	04/18/2018
151 173 Km	SHOES / BACK PADS	ANLU AUTOMOCION SL	04/18/2018
136 489 Km	MECHANICAL WORKMANSHIP	ANLU AUTOMOCION SL	11/03/2017
136 489 Km	LIVE MATERIALS	ANLU AUTOMOCION SL	11/03/2017
136 489 Km	MECHANICS	ANLU AUTOMOCION SL	11/03/2017
136 489 Km	REVISION	ANLU AUTOMOCION SL	11/03/2017
123 604 Km	BODYWORK	ANLU AUTOMOCION SL	07/07/2017
123 604 Km	MECHANICAL WORKMANSHIP	ANLU AUTOMOCION SL	07/07/2017
123 604 Km	LIVE MATERIALS	ANLU AUTOMOCION SL	07/07/2017
123 604 Km	REVISION	ANLU AUTOMOCION SL	07/07/2017
108 575 Km	LIGHT BULBS	ANLU AUTOMOCION SL	03/31/2017
108 575 Km	BODYWORK	ANLU AUTOMOCION SL	03/31/2017
108 575 Km	VARIOUS LIQUIDS	ANLU AUTOMOCION SL	03/31/2017
108 575 Km	MECHANICAL WORKMANSHIP	ANLU AUTOMOCION SL	03/31/2017
108 575 Km	REVISION	ANLU AUTOMOCION SL	03/31/2017
97 122 Km	MECHANICAL WORKMANSHIP	ANLU AUTOMOCION SL	01/09/2017
97 122 Km	FRONT PILLS	ANLU AUTOMOCION SL	01/09/2017
94 578 Km	BODYWORK	ANLU AUTOMOCION SL	12/12/2016
94 578 Km	VARIOUS LIQUIDS	ANLU AUTOMOCION SL	12/12/2016
94 578 Km	MECHANICAL WORKMANSHIP	ANLU AUTOMOCION SL	12/12/2016
94 578 Km	REVISION	ANLU AUTOMOCION SL	12/12/2016
78 773 Km	BODYWORK	ANLU AUTOMOCION SL	07/21/2016
78 773 Km	VARIOUS LIQUIDS	ANLU AUTOMOCION SL	07/21/2016
78 773 Km	MECHANICAL WORKMANSHIP	ANLU AUTOMOCION SL	07/21/2016
78 773 Km	REVISION	ANLU AUTOMOCION SL	07/21/2016

Mileage	Description	Serviced by	Date
61 594 Km	VARIOUS LIQUIDS	RELAUTO CB	03/09/2016
61 594 Km	MECHANICAL WORKMANSHIP	RELAUTO CB	03/09/2016
61 594 Km	REVISION	RELAUTO CB	03/09/2016
48 630 Km	MECHANICAL WORKMANSHIP	AUTOS J RIVADA R SLU	12/22/2015
48 630 Km	FRONT PILLS	AUTOS J RIVADA R SLU	12/22/2015
45 052 Km	VARIOUS LIQUIDS	AUTOS J RIVADA R SLU	11/25/2015
45 052 Km	MECHANICAL WORKMANSHIP	AUTOS J RIVADA R SLU	11/25/2015
45 052 Km	REVISION	AUTOS J RIVADA R SLU	11/25/2015
29 779 Km	OIL FILTER	AUTOS J RIVADA R SLU	08/20/2015
29 779 Km	AIR FILTER	AUTOS J RIVADA R SLU	08/20/2015
29 779 Km	POLLEN FILTER	AUTOS J RIVADA R SLU	08/20/2015
29 779 Km	MECHANICAL WORKMANSHIP	AUTOS J RIVADA R SLU	08/20/2015
29 779 Km	FILLING OIL	AUTOS J RIVADA R SLU	08/20/2015
15 060 Km	MECHANICAL WORKMANSHIP	AUTOS J RIVADA R SLU	05/11/2015
15 060 Km	REVISION	AUTOS J RIVADA R SLU	05/11/2015
10 Km	MECHANICAL WORKMANSHIP	XACOBEO MOTOR SL	02/04/2015